

Status of River Breakages Along River Juba, Somalia August 2019

Region	District	Settlement	Latitude	Longitude	Comment	Status	Length(m)	Latest Image Date	Side of river bank facing downstream
Middle Juba	Bu'aale	Goljano	1.435755	42.423177	There is a breakage at this point as seen on the most recent available image of 02 May 2019.	Open	15	02_May_19	Right
Middle Juba	Bu'aale	Cilmi	1.422436	42.426210	There is a breakage at this point as seen on the most recent available image of 02 May 2019.	Open	9	02_May_19	Left
Middle Juba	Saakow	Sakow	1.659768	42.426527	There is a breakage at this point but with no evidence of recent flooding as at as at 13 June 2019.	Open	10	13_Jun_19	Left
Middle Juba	Saakow	Hilo Amin	1.647112	42.432860	There are no current images available to carry out an assessment at this point. The most current image available of 13 June 2019 is covered with clouds.	Open	5	13_Jun_19	Right
Middle Juba	Saakow	Buurtulle	1.516058	42.435385	There is a breakage at this point but the most recent available image of 13 June 2019 has clouds that hinder assessment of any evidence of recent flooding.	Open	10	02_May_19	Left
Middle Juba	Saakow	Kadaarow	1.613422	42.437120	There is a breakage at this point but with no evidence of recent flooding as at as at 12 August 2019.	Open	8	12_Aug_19	Right
Middle Juba	Bu'aale	Gobate	1.344590	42.459565	There is a breakage at this point with no evidence of intervention as at 02 May 2019.	Open	6	02_May_19	Left
Middle Juba	Saakow	Kuraaw	1.508722	42.466048	There is a breakage at this point but with no evidence of recent flooding based on the most recent available image of 15 April 2019.	Open	2	15_Apr_19	Left
Middle Juba	Bu'aale	Wariin	1.418442	42.434968	There is a breakage at this point as seen on the most recent available image of 02 May 2019.	Open	15	02_May_19	Right
Middle Juba	Saakow	Qaboobe	1.550970	42.447145	There is a breakage at this point but with no evidence of recent flooding as at as at 13 June 2019.	Open	3	13_Jun_19	Right
Middle Juba	Bu'aale	Nadariis	1.407167	42.453073	There is a breakage at this point as seen on the most recent available image of 02 May 2019.	Open	10	02_May_19	Left
Middle Juba	Bu'aale	Gola	1.381007	42.463023	There is a breakage at this point with no evidence of intervention as at 02 May 2019.	Open	3	02_May_19	Left
Middle Juba	Bu'aale	Gola	1.391925	42.464174	There is a breakage at this point with no evidence of intervention as at 02 May 2019.	Open	8	02_May_19	Left
Middle Juba	Bu'aale	Gola	1.269092	42.543033	There is a breakage at this point with no evidence of intervention as at 05 June 2019.	Open	4	05_Jun_19	Left
Middle Juba	Bu'aale	Reebaay	1.267033	42.549542	There are no current images available to carry out an assessment at this point. The most current image available is of 07 July 2019 and it is full of clouds.	Open	6	07_Jul_19	Right
Gedo	Luuq	Heli Shiid	3.804870	42.582510	There is a breakage at this point but with no evidence of recent flooding as at 06 June 2019. The available image is also not very clear as it has some clouds.	Open	8	06_Jun_19	Left
Gedo	Doolow	Bantaal	4.178340	42.112580	There is a breakage at this point but with no evidence of recent flooding as at 19 August 2019.	Open	13	19_Aug_19	Left
Gedo	Doolow	Dollow	4.162168	42.073511	This is a canal intake used for irrigation into the nearby farms that has a potential of causing flooding. There is no evidence of recent flooding as at 19 July 2019.	Open	15	19_Aug_19	Right
Middle Juba	Jilib	Libaanga	0.479164	42.756553	There are no current images available to carry out an assessment at this point. The most current image available of 19 July 2019 is covered with clouds.	Open	22	19_Jul_19	Left
Middle Juba	Bu'aale	Bidi	0.983295	42.623344	There are no current images available to carry out an assessment at this point. The most current image available is of 08 December 2018.	Open	7	08_Dec_18	Left
Middle Juba	Bu'aale	Algooy	0.956989	42.616485	There are no current images available to carry out an assessment at this point. The most current image available is of 08 December 2018.	Open	6	08_Dec_18	Left
Middle Juba	Bu'aale	Mashane	0.822927	42.661194	There are no current images available to carry out an assessment at this point. The most current image available is of 08 December 2018.	Open	6	08_Dec_18	Left
Middle Juba	Jilib	Wagadey	0.687498	42.698229	There are no current images available to carry out an assessment at this point. The most current image available is of 08 December 2018.	Open	15	08_Dec_18	Right
Lower Juba	Jamaame	Moofa	0.160104	42.740313	There are no current images available to carry out an assessment at this point. The most current image available is of 12 February 2019.	Open	10	12_Feb_19	Right
Middle Juba	Jilib	Seylac	0.559515	42.743714	There are no current images available to carry out an assessment at this point. The most current image available is of 06 May 2019 and is full of clouds.	Open	8	06_May_19	Left
Middle Juba	Jilib	Qalaaliyow	0.466152	42.745034	There is a breakage at this point but with no evidence of recent flooding as at 31 July 2019.	Open	6	31_Jul_19	Left
Middle Juba	Jilib	Shangal Duniya	0.388634	42.747033	There is a breakage at this point with no evidence of intervention even though the opening is partially covered with vegetation as at 17 August 2019.	Open	14	17_Aug_19	Left
Lower Juba	Jamaame	Maama	0.161148	42.755833	There are no current images available to carry out an assessment at this point. The most current image available is of 12 February 2019.	Open	6	12_Feb_19	Left
Lower Juba	Jamaame	Makalaago	0.256568	42.756649	There are no current images available to carry out an assessment at this point. The most current image available is of 12 February 2019.	Open	4	12_Feb_19	Right
Lower Juba	Jamaame	Makalaago	0.256963	42.764729	There are no current images available to carry out an assessment at this point. The most current image available is of 12 February 2019.	Open	22	12_Feb_19	Right
Middle Juba	Jilib	Madhooka	0.552432	42.765250	There are no current images available to carry out an assessment at this point. The most current image available is of 06 May 2019 and is full of clouds.	Open	7	06_May_19	Left
Middle Juba	Jilib	Nasiib Buundo	0.341995	42.767378	There is a breakage at this point as seen on the most recent available image of 17 August 2019.	Open	18	17_Aug_19	Right
Middle Juba	Bu'aale	Jubba	1.449290	42.420860	There is a breakage at this point as seen on the most recent available image of 02 April 2019.	Open	9	02_Apr_19	Left
Middle Juba	Bu'aale	Nadariis	1.405970	42.454780	The most current image available of 02 May 2019 is full of clouds. The point is covered with vegetation that hinders assessment but there is no evidence of intervention as at 02 April 2019.	Open	5	02_Apr_19	Left
Middle Juba	Bu'aale	Cismaan yarow	1.226320	42.558860	Vegetation cover hinders assessment of the embankment but the point neither shows evidence of recent flooding nor of any intervention as at June 2019.	Open	13	16_Jun_19	Left
Middle Juba	Saakow	Qaboobe	1.550130	42.441870	There is a breakage at this point but with no evidence of recent flooding as at as at 13 June 2019.	Open	5	13_Jun_19	Right
Lower Juba	Jamaame	Sunguuni	0.004870	42.660080	This is an opening created to allow water passage for irrigation.	Open	20	06_Jun_19	Right
Lower Juba	Jamaame	Malayle	-0.004500	42.655820	There is a breakage at this point as seen on the most recent available image of 06 June 2019.	Open	16	06_Jun_19	Right
Lower Juba	Jamaame	Jibey	-0.011240	42.657970	This point has an opening and should be monitored because there is no intervention since the flooding of June 2018.	Open	5	06_Jun_19	Right
Lower Juba	Jamaame	Jibey	-0.010920	42.658990	There is a breakage at this point as seen on the most recent available image of 06 June 2019.	Open	14	06_Jun_19	Right
Lower Juba	Jamaame	Jibey	-0.013050	42.665920	There is a breakage at this point with no evidence of intervention even though the opening is partially covered with vegetation as at 06 June 2019.	Open	4	06_Jun_19	Left
Lower Juba	Jamaame	Juwaaley	-0.035720	42.610470	There is a breakage at this point with no evidence of intervention as at 06 June 2019.	Open	5	06_Jun_19	Left
Lower Juba	Jamaame	Gaduud	-0.060890	42.592850	There is a breakage at this point with no evidence of intervention even though the opening is partially covered with vegetation as at 12 June 2019.	Open	10	12_Jun_19	Right
Lower Juba	Kismaayo	Gaduud	-0.070970	42.587800	There is a breakage at this point with no evidence of intervention as at 12 June 2019.	Open	17	12_Jun_19	Right
Lower Juba	Kismaayo	Gaduud	-0.063460	42.587080	There is a breakage at this point as observed on the image of 12 June 2019.	Open	8	12_Jun_19	Right