

## Status of River Breakages Along River Shabelle, Somalia August 2019

Region	District	Settlement	Latitude	Longitude	Comment	Status	Length(m)	Latest Image Date	Side of river bank facing downstream
Hiraan	Bulo Burto	Samataro	4.34800	45.37270	There was flooding at this site noted in 30 June 2018. However, since then there is no evidence of floods or of an intervention as at 01 May 2019.	Open	5	01_May_19	Right
Hiraan	Bulo Burto	Jaaboole Bari	3.82214	45.56290	There is evidence of flooding at this site noted in May 2019. There is no evidence of an intervention as at 12 July 2019.	Open	9	12_Jul_19	Right
Middle Shabelle	Balcad	Gaashaanle	2.64442	45.50775	There is no evidence of recent flooding at this point as seen in the images of 23 January 2019 and Feb 2019. No signs of intervention, current images are needed.	Open	26	28_Feb_19	Left
Middle Shabelle	Balcad	Muku Dheere	2.43538	45.46735	There was sandbag intervention implemented at this site in August 2017. There is some evidence of flooding on Jan 2019. Sand deposits - seen in the image of 05 July 2019.	Open	12	05_Jul_19	Left
Hiraan	Belet Weyne	Hilo Kelyo	4.78876	45.21617	This breakage was fixed through Soil heaping using heavy machinery by FAO in January 2019. Although the image of 23 May 2019 showed limited flooding due to water spillage over the heaped soil	Open	0	23_May_19	Left
Lower Shabelle	Afgooye	Bariire	2.05591	44.90789	There is no evidence of flooding at this point as at 19 July 2019. Vegetation cover hinders proper assessment for any intervention.	Open	3	19_Jul_19	Right
Hiraan	Jalalaqsi	Mohamud Baroole	3.29057	45.55157	There are no current images available to make an assessment for this site. Most up-to-date image is 25 February 2019	Open	13	25_Feb_19	Left
Hiraan	Jalalaqsi	Bacadley	3.29058	45.55681	There was a breakage at this site, which caused flooding into the nearby farms in June 2018. As at 08 July 2019, there is no evidence of an intervention or of any recent floods.	Open	9	08_Jul_19	Right
Hiraan	Bulo Burto	Jameeco	4.30180	45.38026	There is an open breakage at this point as noted in April 2018. As at 01 May 2019 there is no evidence of recent flooding nor of an intervention implemented.	Open	14	01_May_19	Right
Hiraan	Bulo Burto	Jameeco	4.29469	45.38588	There is an open breakage at this point as noted in April 2018. As at 01 May 2019 there is no evidence of recent flooding nor of an intervention implemented.	Open	14	01_May_19	Right
Hiraan	Belet Weyne	Doolo Biciid	4.38093	45.35103	There is no evidence of recent flooding nor of an intervention at this site as at 01 May 2019.	Open	6	01_May_19	Right
Hiraan	Bulo Burto	Doonkaxare	4.15188	45.47089	There is no evidence of recent flooding nor of an intervention at this part as at 28 April 2019. Current images are needed to make further analysis.	Open	8	28_Apr_19	Right
Hiraan	Bulo Burto	Cadey-Jameeco	4.17304	45.43174	There are no current images available to make an assessment for this site, April 2019 image is cloudy. Most up-to-date image is 08 September 2018.	Open	8	08_Sept_18	Right
Hiraan	Bulo Burto	Cadey-Jameeco	4.18766	45.42113	There are no current images available to make an assessment for this site, April 2019 image is cloudy. Most up-to-date image is 08 September 2018.	Open	9	08_Sept_18	Right
Hiraan	Bulo Burto	Bur Dooxo	4.19134	45.42051	There are no current images available to make an assessment for this site, April 2019 image is cloudy. Most up-to-date image is 08 September 2018.	Open	7	08_Sept_18	Left
Hiraan	Bulo Burto	Bur Dooxo	4.19654	45.41688	There are no current images available to make an assessment for this site. Most up-to-date image is 08 September 2018. April 2019 image is cloudy.	Open	5	08_Sept_18	Left
Hiraan	Bulo Burto	Helo-Banaan	4.12576	45.48441	There are no current images available to make an assessment for this site. Most up-to-date image is 23 October 2018.	Open	13	23_Oct_18	Right
Hiraan	Bulo Burto	Bulo Burto	3.85765	45.56684	This point is a canal intake. In June 2018 it was the origin of floods at this area. As at 06 June 2019 there is no evidence of an intervention implemented here or signs of flooding.	Open	5	06_Jun_19	Right
Hiraan	Jalalaqsi	Bukuraale	3.23909	45.53976	There is no evidence of flooding nor of an intervention at this site as at 08 July 2019. There was a breakage at this site noted in 2017 and 2018. Site is still open.	Open	7	08_Jul_19	Right
Middle Shabelle	Jowhar	Duduble	3.14874	45.53634	There are no current images available to make an assessment for this site. Most up-to-date image is 25 February 2019	Open	8	25_Feb_19	Right
Lower Shabelle	Qoryooley	Dhaayaney	1.80254	44.65406	There is no evidence of recent floods at this point as at 27 June 2019. Vegetation cover hinders assessment of an intervention.	Open	6	27_Jun_19	Right
Hiraan	Belet Weyne	Horseed	4.73339	45.22296	Flooding resulted from this point onto the nearby farms in April 2018. As at 23 May 2019, there is no evidence of recent flooding nor of an intervention.	Open	18	23_May_19	Left
Middle Shabelle	Jowhar	Buulo axmed	2.89779	45.54783	There is water spillage into the farm from this point noted in images of January and February 2019. The next available image of March 2019 does not show intervention. Current images are needed for further assessment.	Open	15	30_Mar_19	Left
Middle Shabelle	Jowhar	Duduble	3.15422	45.55355	There are no current images available to make an assessment for this site. Most up-to-date image is 25 February 2019.	Open	19	25_Feb_19	Left
Hiraan	Belet Weyne	Dolo madow	4.86277	45.10123	There are no current images available to make an assessment for this site. Most up-to-date image is 21 November 2018	Open	3	21_Nov_18	Right
Lower Shabelle	Qoryooley	Mashalaay	1.74498	44.60010	There was flooding at this site May 2018. As at 08 March 2019 there is no evidence of recent flooding. Current images are needed to make further analysis most current is March 2019.	Open	6	21_Mar_19	Right
Middle Shabelle	Jowhar	Hurway	3.11631	45.54678	This is a canal intake, water from this point caused flooding in the nearby farms in May 2018. As at 25 April 2019, there is no evidence of recent flooding. Current images needed for further analysis.	Open	3	25_Apr_19	Right
Middle Shabelle	Balcad	Balcad	2.36113	45.39683	There is no evidence of flooding or an intervention as at 08 April 2019. Current images are needed to make better assessment of this site. Most current of April and June have cloud cover.	Open	4	01_May_19	Right
Hiraan	Belet Weyne	Goonyaale	4.36412	45.36253	There is no evidence of recent floods at this site as at 01 May 2019.	Open	15	01_May_19	Right
Middle Shabelle	Balcad	Balcad	2.38859	45.42095	A breakage was noted at this site in April 2018 and Nov 2018. There is no evidence of an intervention as at 02 July 2019.	Open	5	02_Jul_19	Left
Lower Shabelle	Kurtunwaarey	Habaabshe	1.64646	44.34886	There are no current images available to make an assessment for this site. Most up-to-date image is 26 November 2018	Open	20	26_Nov_18	Left
Hiraan	Belet Weyne	Doolo biciid	4.38838	45.34882	There is no evidence of recent flooding nor of an intervention at this site as at 01 May 2019.	Open	5	01_May_19	Left
Hiraan	Belet Weyne	Doolo Biciid	4.38713	45.34928	There is no evidence of recent of flooding nor of an intervention at this site as at 01 May 2019.	Open	5	01_May_19	Left
Hiraan	Jalalaqsi	Buulo Qodaxleey	3.44374	45.62557	There is no evidence of an intervention or flooding at this site as of 16 March 2019. Current images are needed to make further assessment of this site.	Open	4	16_Mar_19	Left
Middle Shabelle	Jowhar	Diinlaawe	3.03740	45.50132	There are no current images available to make an assessment for this site. Most up-to-date image is 16 September 2018	Open	11	16_Sept_18	Right
Middle Shabelle	Jowhar	Diinlaawe	3.03667	45.50191	There is no evidence of recent flooding nor of an intervention at this site. Current images are needed to make further assessment for this part. Most current image is of 02 March 2019.	Open	5	02_Mar_19	Left
Middle Shabelle	Jowhar	Diinlaawe	3.03197	45.50265	There is no evidence of recent flooding nor of an intervention at this site. Current images are needed to make further assessment for this part. Most current image is of 02 March 2019.	Open	5	02_Mar_19	Right
Middle Shabelle	Balcad	Sheekh Hintire	2.56202	45.49687	There are breakages along the canal at this site. There is however no evidence of recent floods nor of any interventions as at 06 July 2019. The site however needs to be closely monitored.	Open	7	06_Jul_19	Left
Lower Shabelle	Qoryooley	Cabdi abuukar	1.71723	44.44327	This part of the embankment it is open, could be canal intake points. As at 06 May 2019 there is no evidence of recent flooding nor of an intervention.	Open	25	06_May_19	Right